

US EPA ARCHIVE DOCUMENT

## LANDFILL SITE ASSESSMENT

Facility Name :	Clearview Waste Management Landfill	Facility Location ID :	110002225976
Assessment Date :	9/3/2010	Incident Name :	BP Spill
Physical Location :	2253 Mudline Road		
City, State :	Lake , MS	County :	Scott

## ASSESSMENT INFORMATION

General Site Information and Observations	
1. Is the facility currently receiving debris from BP?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. If no, has the facility received debris from BP in the past?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Which companies are transporting the BP waste?	Waste Management
4. How many BP waste loads have been rejected?	None
5. If so, why?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
<b>Additional Comments :</b> During this operational period John E. Johnston departed for the Clearview Landfill, Lake, Scott County, Mississippi at 1030 hours CDT for an EPA assessment of the waste accepted at the facility. Jason Bridges (MDEQ) was invited to participate in the visit but could not attend. The Waste Monitoring Group Supervisor arrived at the landfill at 1345. Jim Johnston, Operations Manager, was present during the Waste Monitoring Group assessment at the Clearview Landfill. Only three loads arrived today.	